ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli

Street ID	Street Name	Significant Landmark
W0137, W0125, W0127, W0135, W0133, W0158, W0141, W	NA, Veera Anjaneya Temple Rd, Vinayaka Lyt 4th Crs, Om Shakthi Lyt 3rd Crs, Om Shakthi Lyt 4th Crs,	Vijayalakshmi Layout AGB Layout Lakshmi temple sur

Segment No.	Total Length (m)
12/C-W0137/S035143	1273.41

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	260.40	77.525784	13.073582	77.528159	13.073232	W0158	W0158
2	261.87	77.525672	13.074203	77.528058	13.073839	W0156	W0156
3	242.56	77.525749	13.074836	77.527972	13.074593	W0114	W0114
4	272.12	77.518877	13.077796	77.521359	13.077433	W0118	W0118
5	236.46	77.519512	13.077362	77.521671	13.077069	W0124	W0124

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Maintenance of UGD in ward no.12 Shettyhalli, Shettyhalli Sub Sub Division	3000000	2020

Year	Type of Work	Other Work Type
2020 - 2021	Others	Sanitary linking UGD work

Tender	Work Details	Job No. / Work Code
Tender		012-20-000004

Work Order No.	Work Order Date	Period of Extention
EE/DD/WO/481/2019-20	02/01/2020	

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
02/06/2020	03/06/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Mahendra Engineering Works		31988630.00

Phone No.	E-Mail ID

Zone: DASARAHALLI Ward No: 12 Ward Name: Shettihalli Street ID: W0137, W0125, W0127, W0135,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.

Scanned by CamScanner

9448203712

Field Inspection Details

Number of Trees	Any Other Information	Name
2	ugd works	maintanance of ugd works in ward no 12

Date of Inspection	Remarks
28/01/2021	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: DASARAHALLI Ward No: 12 Ward Name: Shettihalli Street ID: W0137, W0125, W0127, W0135,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.

Scanned by CamScanner